

JOB RECORD

CPE - JR - 2026 - 000001

WORK ORDER # WO-0147
RECORD DATE (UPLOAD) 2026-08-15 22:04:51 UTC (server-recorded)
CREW Travis B.
CREW ATTESTATION ✓ "I took these photos today at this job."
JOB TYPE ☐ Service call ☒ Panel / breaker ☐ Underground / trench ☐ Lighting
☐ Wiring / remodel ☐ Other
As entered: panel / breaker upgrade

Free-text job description is excluded from Job Records; structured fields only.

TIME ON RECORD — TWO CLOCKS

Photo 1 (IMG_5147.jpg) — taken: 2026-08-15 15:47:12 (device-reported, EXIF)
Photo 2 (IMG_5148.jpg) — taken: 2026-08-15 15:47:58 (device-reported, EXIF)
Photo 3 (IMG_5149.jpg) — taken: 2026-08-15 15:48:31 (device-reported, EXIF)
Photo 4 (IMG_5150.jpg) — taken: 2026-08-15 15:49:05 (device-reported, EXIF)

Uploaded: 2026-08-15 22:04:51 UTC (server-recorded on receipt)

UPLOAD LOCATION (DEVICE-REPORTED, APPROXIMATE)

43.61871° N, 116.21460° W (decimal: 43.61871, -116.21460)

PHOTOS ON THIS RECORD (4)




Photo 1



Photo 2



Photo 3



Photo 4

Full-size originals, capture times, and hashes follow — one page per photo.



Taken: 2026-08-15 15:47:12 (device-reported, EXIF) · Uploaded: 2026-08-15 22:04:51 UTC (server-recorded)


SHA-256 d55a2851c01c0ada024dcd597880f0920cc383855d82163e13d58b4884fb11ee

Before/after designation was not recorded at upload; photos appear in upload order.



Taken: 2026-08-15 15:47:58 (device-reported, EXIF) · Uploaded: 2026-08-15 22:04:51 UTC (server-recorded)

SHA-256 83fe76398e8e7afab97d82fcb629286107250f406387216b3142c6d35a508663



Taken: 2026-08-15 15:48:31 (device-reported, EXIF) · Uploaded: 2026-08-15 22:04:51 UTC (server-recorded)

SHA-256 e89714eb952f2cb900ebcf380864f510133e7d2119cf254fd93a756a2660d9ee



Taken: 2026-08-15 15:49:05 (device-reported, EXIF) · Uploaded: 2026-08-15 22:04:51 UTC (server-recorded)

SHA-256 92e5c72efddb32c1d34fbeb49c7bfa48c3019829c417518d194751b614a51c

PROVENANCE & FILE HASHES

Unedited original photos (SHA-256):

IMG_5147.jpg	d55a2851c01c0ada024dcd597880f0920cc383855d82163e13d58b4884fb11ee
IMG_5148.jpg	83fe76398e8e7afab97d82fcb629286107250f406387216b3142c6d35a508663
IMG_5149.jpg	e89714eb952f2cb900ebcf380864f510133e7d2119cf254fd93a756a2660d9ee
IMG_5150.jpg	92e5c72efddb32c1d34fbeb49c7bfa48c3019829c417518d194751b614a51c

This document (SHA-256 of rendered content, pre-stamp):

dfd82075991240368797c1c6996510e50f05824a8496716f81f0b8df114d1d2f

This Job Record (CPE-JR-2026-000001) was generated automatically by the Copper Peak Electric photo portal when the crew upload was received. Photo capture times come from the image files' EXIF data and are device-reported. The upload time was recorded by the portal server when the files arrived. The upload location, when present, is the upload location as reported by the uploading device, and is approximate. Each photo hash is the SHA-256 digest of the unedited original file as received. The document hash above is the SHA-256 digest of this record's content as rendered before that hash was stamped onto this page; stamping changes the file's bytes, so the final file's own digest is recorded in the client ledger next to this record. This record was filed to the client's records page on the portal; the archived copy is write-once. Record filed: 2026-08-15 22:05:03 UTC.